



EXHIBIT NO. 13
DATE 3-22-11
BILL NO. HB 315



Right Side of Case Boiler Showing Construction of Butt and Double Strap Joint



Cross Section of Boiler




Fig. 1—Lap Joint




Fig. 2—Butt and Double Strap Joint

Dick Tombrink

2250 N 12th Rd

Worden, MT 59088

690-4080 cell

967-6687 home

dicknsue@nemontel.net